

## PRELIMINARY SUMMARY OF MAP ACTIONS

Community: HARRISON COUNTY

Community No: 180085

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

### 1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

### 2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	98-05-5532A	08/19/1998	5050 ELWANGER ROAD, N.E.	1800850004B	18061C0140C
LOMA	02-05-2273A	04/19/2002	PART OF NW1/4 OF SECTION 13, T3S R2E; 3100 BURGESS CIRCLE ROAD N.W.	1800850003B	18061C0125C
LOMA	02-05-3478A	07/03/2002	PART OF SECTION 23, TOWNSHIP 2S, RANGE 4E; 4314 EAST WHISKEY RUN ROAD	1800850004B	18061C0135C
LOMA	04-05-A497A	08/23/2004	4940 ELWANGER ROAD NE -- PORTION OF SECTION 8, T3S, R4E	1800850004B	18061C0140C
LOMA	07-05-4555A	09/11/2007	PORTION OF SECTION 4, T4S, R3E -- 3370 MATHIS ROAD SW (IN)	1800850007B	18061C0205C

### 3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

## PRELIMINARY SUMMARY OF MAP ACTIONS

Community: HARRISON COUNTY

Community No: 180085

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

**4. LOMCs To Be Redetermined**

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	01-05-3238A	08/15/2001	3845 BLUE SPRINGS ROAD CENTRAL	1800850006B	18061C0285C
LOMA	01-05-3013A	08/22/2001	4755 ROCKY HOLLOW ROAD	1800850006B	18061C0215C
LOMA	02-05-0765X	12/14/2001	PORTION OF SECTION 36, TOWNSHIP 4 SOUTH, RANGE 2 EAST; 5845 BLUE SPRINGS ROAD	1800850006B	18061C0285C
LOMA	03-05-2192A	06/18/2003	PORTION OF SECTION 36, T4S, R5E; 5295 HIGHWAY 111 SOUTHEAST	1800850008B	18061C0375C
LOMA	04-05-0813A	12/31/2003	PART OF FRAC. SECTION 24, T4S, R5E; 3685 HIGHWAY 111 S.E.	1800850008B	18061C0270C
LOMA	04-05-2565A	05/19/2004	TRACT 2; 3755 AND 3757 HIGHWAY 111 SE	1800850008B	18061C0270C
LOMA	07-05-2133A	03/08/2007	11360 LOPP CIRCLE ROAD SW -- PORTION OF SECTION 34, T5S, R3E (IN)	1800850010B	18061C0320C
LOMA	08-05-1687A	02/26/2008	11825 HIGHWAY 111 SE -- PORTION OF SECTION 35, T5S, R5E	1800850011B	18061C0375C
LOMA	08-05-2357A	03/27/2008	3755/3757 HIGHWAY 111 SE -- PORTION OF SECTION 24, T4S, R5E	1800850008B	18061C0270C
LOMA	10-05-0415A	12/28/2009	11405 HIGHWAY 111 SOUTHEAST	1800850011B	18061C0375C